# **Operating Instructions for 3 mm Evacuable Dies**

## Parts supplied:

- 1 Sleeve with evacuation tube
- 2 & 3 Stepped pellets
- 4 Funnel for loading sample
- 5 Sample extractor
- 6 V-mount slide holder

### **PLEASE NOTE:**

Pmax 3 mm = 0.5 tons!

### Step 1

After ensuring that all parts are clean, assemble one stepped pellet to the vacum tube end of the sleeve (die body).

### Step 2


Place the load funnel into the opposite end of the die body.

Do not overfill bore of die body with sample. Leave about 1.0-1.5 mm for location of the second stepped pellet.

Release the vacuum and remove the vacuum tube.

Remove both stepped pellets. The V-mount will hold the die body for analysis in a spectrophotometer.

After analysis, the sample is removed from the die body by means of the sample extractor. After use clean all parts thoroughly.



We reserve the right to change technical specifications without notice. Copyright © msscientific Chromatographie-Handel GmbH  $\cdot$  All rights reserved

Fon: +49 30 6270 6087 Fax: +49 30 6270 6089

E-mail: info@msscientific.de • Web: www.msscientific.de